Friday, February 24, 2012 1:13:57 PM

79910

Page 1

Item ID: D350-561-143 Accept *N900040100* Setup Start **Revision ID:** Dual Cargo Mirror Installation, RH Item Name: Start Qty: 1.00 **Start Date:** 2/8/2012 **Cust Item ID:** Required Date: 2/9/2012 **Req'd Qty:** 1.00 **Customer:** CU-DAR001 RMA RAILI310 - RETURN - DISASSEMBLE Reference: Run Date: 12-02-24 Tooling: Process Plan: Approvals: Date: QC: SPC (Y/N): Date: Date: Sequence ID/ Operation Tool ID Set Up/ Tool # Plan Reject Accept Reject Insp. Work Center ID Description **Run Hours** Code **Qty Qty** Number Stamp **Draw Nbr Revision Nbr** D350-561 Rev D 100 0.00 *100* 78 N QC 0.00 Memo Quality Control INSPECT RA 111310 D350-561-143 B 73152 Sizloglo, KIT HAS BEEN INSTALLED. GIVE ALL HARDWARE BACK TO ENG EXCEPT: D2012-105 X I B 74129 1 D2011-101 X 1 B 70729 AV D3646-1 X 1 B 70762 D3646-3 X 1 B 70763

110

110

Packaging

Memo

0.00

Packaging

RETURN PARTS IN STOCK UNDER ORIGINAL BATCH NUMBER

RETURN TO STOCK UNDER ORIGINAL BATCH NUMBERS

0.00

(44/3/2 (V)

Work Order ID 79910

Friday, February 24, 2012 1:13:57 PM

2/8/2012

Item ID: D350-561-143 **Revision ID:**

Accept

N900040100

Setup Start

Item Name:

Start Date:

Dual Cargo Mirror Installation, RH

Start Qty: 1.00

Req'd Qty: 1.00

1

Cust Item ID:

Customer:

CU-DAR001

Reference:

Approvals:

RMA RA111310

Date:

Date:

Tooling:

Date:

Run

Required Date: 2/9/2012

Process Plan:

QC:

SPC (Y/N):

Date:

Sequence ID/

Operation Description Set Up/ **Run Hours** Tool ID

Tool # Plan

Reject Accept

Reject

Insp.

Work Center ID 120

QC21- Final Inspection - Work Order Release

0.00

Code

Qty

Qty

Number Stamp

120 QC

Memo

0.00

MLJ 12/63/02

Quality Control

Picklist Print

Friday, February 24, 2012 1:13:57 PM

Work Order ID:

79910

Parent Item:

D350-561-143

Parent Item Name:

Dual Cargo Mirror Installation, RH

Start Date: 2/8/2012

Required Date: 2/9/2012

Start Qty: 1.00

Required Qty: 1.00

Comments:

IPP A 07.07.26 new issue (DS19379) EC

523 EC verified by: DD

525 EC Verified by DD													
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measur		Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2011-101 6" Mirror		Manufactured	No				Each	53.0000		(+)) 7	129	all .
				Location		Loc Qty	I	Loc Code			•		
				ST226		53							
				7598	33	11							
				7994		42						1	1
D2012-105 Arm		Manufactured	No				Each	6.0000		-1	74/2	م کرد	
				Location		Loc Qty	L	oc Code			,	, ,	•
				ST229		6							
				7072	25	6						/	
D3646-1		Manufactured	No			v	Each	9.0000					
Arm		Manufactured						710000		-1		1/	
				Location		Loc Qty	L	oc Code			_		
				ST229		9							
				7076	2	1			70	762			
				7626	3	8				100		/	1
D3646-3		Manufactured	No				Each	11.0000		-1 ,	7. 7.	2 1	
Arm											10 16	3/6	Z
·			•	Location		Loc Qty	L	oc Code				C	
				ST229		11	_						
				7076		1			-				
				7413		4							
						•							

6

79356

verified by:JLM IPP rev B 10.02.16 per ecn 10-

Page 1

RA 111310 D350-561-143 B73152

Received @ Dart January 31st, 2012 Inspected@ Dart February 3rd, 2012

Instructions for RA 111310 D350-561-143 B73152 CHG003

- Kit has been installed
- Give all hard ware to Engineering except
 - o D2012-105 B74129
 - o D2011-101 B70729
 - o D3646-1 B70762
 - o D3646-3 B70763
- Return back to stock under original BATCH #'s

<u>Time Estimate</u> = 1 HOUR ONLY (stores)

Departments Required: Stores (restocking)

<u>Pictures Attached</u> = YES

THIS INSTRUCTION SHEET MUST BE ATTACHED TO THE RESTOCKING WORK ORDER AT ALL TIMES!!!!

3/2